




OREGON U-FORM 7(3,4)5(1,2)10




PZ2, 10 mm

With a sleep function


With a storage box

A 4 pcs	B 13 pcs	C 5x45mm 12 pcs	D 5x60mm 10 pcs	E 5x35mm 3 pcs	F 6x80mm 4 pcs	G M8 4 pcs
H 1 pcs	I 1 pcs	J 1 pcs	K 1 pcs	L 1 pcs		


Step 1



Step 2




Step 3




B

K




Step 4




B


L




A




Step 5



F



Step 6



6a

